FCAL1 Process Sheet

T.Embry/P.Loch/L.Shaver

Process Spec: 1.3.3.1.1.1 – Tube Shipment Acceptance

Inspection

Components: Copper Tube [4.2.7.1.2.1]

Material:

Tooling:

Location: UofA PAS 180

QC Form:

Process:

- 1. Record packaging (number of boxes/containers) and approximate total number of shipped tubes.
- 2. Inspect container(s) and boxes. Record damages and conditions.
- 3. **(1.3.3.1.1.2-1)** Visual tube inspection of 1 box of tubes.
- 4. **(1.3.3.1.1.1-1)** Tube dimension inspection for 200 randomly selected tubes from various boxes.
- 5. Reject shipment if number of unacceptable tubes is larger than 10% of total shipment.

Remarks:

Rejection criteria are preliminary.

Global Process: <u>1.3.3.1.1</u> – Tube Procedures

Previous: none

Follow-Up: <u>1.3.3.1.1.2</u> – Tube Processing